

## Overview

ICS Industries were engaged by Telstra to commence repairs on their Roadside Cabinets.



1. Damaged doors subframe and knocked 100mm out of plumb (leaning over)



2. Damaged doors on cabinet leaning forward and stopping door from fully opening



3. Repair included refitted doors, instruction panels and DA numbering



4. Work completed with new doors and straightened frame